

<u>Location of Asbestos Containing Material (ACM)</u>	<u>Type of ACM</u>	<u>Approx. Area of ACM</u>	<u>Date of Original Inspection</u>	<u>Date of Last Inspection</u>	<u>Material Assessment</u>	<u>Risk of Disturbance</u>	<u>Condition</u>	<u>Action</u>
Bitumen adhesive present under two layers of floor lino in Large Hall Vestibule	White Asbestos	Approx. 30 m2	May-17	Jan-24	Unknown	Minimal	Satisfactory	None required at present.
External soffits above the entrance to the halls and over the fire escape door next to the boiler house	White Asbestos	Approx. 4 m2	May-17	Jan-24	Fair	Minimal	Satisfactory	None required at present.